## Weott CSD's Operator's Report 2-21-24 Kyle and Greg

Springs/Flow: The spring box for A side has plugged up with sediment and rocks multiple times in the past month because of heavy rain. Each time Tommy has to take us across on his jet boat because the river is too high and grass hopper road is closed because of a giant tree blocking the road. A flow is slowing down as of 2/20 so we will have to go across and clean springs out again.

Test Results: Water quality has been passing state standards.

Water Plant: We set up a new Coagulant system for A side to help with lowering the turbidity. It has been working a lot more efficiently.

Road to Springs: We talked to state park personnel about the blockage on the grasshopper access road, and they said they may be able to help out with clearing it when it dries up some. So we don't have to pay someone to take us across every time the springs clog.

Wastewater Plant: The wastewater treatment plant filtering bed has a difficult time keeping up with the rain during these heavy storms because we have only one operating bed.

**Wastewater Treatment:** Wastewater has been passing state standards.

Wastewater Road: We have noticed the access road to the plant is dropping out. There is a good size hole underneath one section of the road. It will need to be repaired before we have any Fuel trucks or equipment brought down there.